

TIFFIN AIRE



1778 W US 224, Tiffin, Ohio 44883
 Phone: 800-458-2487 Fax: 419-447-4042
 Contact: Andrew Newman

SMR ICE SHIELD DE-ICE BOOTS INTRODUCING ICE SHIELD™ AIRCRAFT DE-ICING SYSTEMS FOR NEWER AIRCRAFT

Certified Ice Shield™ Aircraft De-Icing Systems are
 FAA, STC/PMA approved for the following aircraft:

- Beechcraft
- Cessna
- DeHavilland
- Dornier
- Embraer
- Fairchild
- Jetstream
- Mitsubishi
- Pilatus
- Piper
- Twin Commander
- Vulcanair Partenavia

ICE SHIELD PNEUMATIC DE-ICERS BY AIRCRAFT

Beech (Raytheon) A36 Bonanza

A36	A36TC	A36		Location:	Goodrich P/N:	SMR PN:	List:	Your Cost:
*X	X			Wing – LH	25S-5D5129-01	SMR5129-01	\$4394	Please call
*X	X			Wing – RH	25S-5D5129-02	SMR5129-02	\$4394	Please call
X	X	X		Horiz Stab – LH	25S-5D5129-03	SMR5129-03	\$2679	Please call
X	X	X		Horiz Stab – RH	25S-5D5129-04	SMR5129-04	\$2679	Please call
		*X		Wing – LH	25S-5D5129-05	SMR5129-05	\$6332	Please call
		*X		Wing – RH	25S-5D5129-06	SMR5129-06	\$6332	Please call

*Verify Cut Out

Beech (Raytheon) 55 Baron

55,A55,B55,B55A C55,C55A	D55,D55A	E55	E55A	Location	Goodrich P/N:	SMR PN	List:	Your Cost:
X				Light – Tip – LH	23S-2004-2-1	SMR2004-2-1	\$4502	Please call
X				Light – Tip – RH	23S-2004-2-2	SMR2004-2-2	\$3489	Please call
X				Horiz Stab – LH	23S-2004-5-1	SMR2004-5-1	\$3093	Please call
X				Horiz Stab – RH	23S-2004-5-2	SMR2004-5-2	\$3093	Please call
X	X	X	X*	Vertical Fin	23S-2004-7-1	SMR2004-7-1	\$2442	Please call
X	X			Nac – Tip – LH	23S-2004-14-1	SMR2004-14-1	\$5641	Please call
X	X			Nac – Tip – RH	23S-2004-14-2	SMR2004-14-2	\$5641	Please call
	X	X	X**	Horiz Stab – LH	23S-2004-15-1	SMR2004-15-1	\$2373	Please call
	X	X	X**	Horiz Stab – RH	23S-2004-15-2	SMR2004-15-2	\$2387	Please call
		X	X	Nac – Tip – LH	23S-2004-17-1	SMR2004-17-1	\$4662	Please call
		X	X	Nac – Tip – RH	23S-2004-17-2	SMR2004-17-2	\$4662	Please call

FAA requires de-ice boots to be replaced in pairs for all Ice Shield 2 part numbers (replacement option for Goodrich tube-type de-icers).

*S/N TE-768 – TE937

**S/N TE-768 – TE977

Beech (Raytheon) 55 Baron

95-B55/B55A	95-C55/C55A	E55/E55A	Location:	Goodrich P/N:	SMR PN:	List:	Your Cost:
TC-1657, TC-1699, TC-1701 & Up	TE-1 – TE-451 TC-350	TE978 & Up					
X		X	Wing – LH	25S-7D5057-01	SMR5057-01	\$5126	Please call
X		X	Wing – RH	25S-7D5057-02	SMR5057-02	\$5126	Please call
X	X	X	Horiz Stab – LH	25S-7D5057-03	SMR5057-03	\$3394	Please call
X	X	X	Horiz Stab – RH	25S-7D5057-04	SMR5057-04	\$3394	Please call
		X	Horiz Stab – LH	25S-7D5057-07	SMR5057-07	\$2673	Please call
		X	Horiz Stab – RH	25S-7D5057-08	SMR5057-08	\$2673	Please call
X	X	X	Vertical Fin	25S-7D5057-09	SMR5057-09	\$2775	Please call

Beech (Raytheon) 56 and 58 Baron

56TC	A56TC	58,58A		Location:	Goodrich P/N:	SMR P/N:	List:	Your Cost:
	CG78 Up							
X	X	X		Vertical Fin	23S-2004-7-1	SMR2004-7-1	\$2442	Please call
X	X	X		Horiz Stab – LH	23S-2004-15-1	SMR2004-15-1	\$2373	Please call
X	X	X		Horiz Stab – RH	23S-2004-15-2	SMR2004-15-2	\$2387	Please call
X	X			Nac – Tip – LH	23S-2124-4-1	SMR2124-4-1	\$5358	Please call
X	X			Nac – Tip – RH	23S-2124-4-2	SMR2124-4-2	\$5358	Please call
X	X*	X		Nac – Tip – LH	23S-2124-5-1	SMR2124-5-1	\$5973	Please call
X	X*	X		Nac – Tip – RH	23S-2124-5-2	SMR2124-5-2	\$5358	Please call

FAA requires de-ice boots to be replaced in pairs for all Ice Shield 2 part numbers (replacement option for Goodrich tube-type de-icers).
 *Check PMA TG78 & Up

Beech (Raytheon) 58 Baron

58TC/58TCA	58P/58PA			Location:	Goodrich P/N:	SMR P/N:	List:	Your Cost:
ALL – TK-1 Up	TJ-3 – TJ-31, TJ-33 – TJ-37	TJ-32, TJ-38 Up						
	X			Wing - LH	25S-7D5057-01	SMR5057-01	\$5126	Please call
	X			Wing – RH	25S-7D5057-02	SMR5057-02	\$5126	Please call
X	X	X		Horiz Stab – LH	25S-7D5057-07	SMR5057-07	\$2673	Please call
X	X	X		Horiz Stab – RH	25S-7D5057-08	SMR5057-08	\$2673	Please call
X	X	X		Vertical Fin	25S-7D5057-09	SMR5057-09	\$2775	Please call
X		X		Wing – LH	25S-7D5057-11	SMR5057-11	\$5689	Please call
X		X		Wing – RH	25S-7D5057-12	SMR5057-12	\$5689	Please call

Beech (Raytheon) 58 Baron

58				G58		Location:	Goodrich P/N:	SMR P/N:	List:	Your Cost:
TH-1 – TH-370	TH-371 – TH-460	TH-461 – TH-668	TH-669, TH-680 – TH-2124	TH-2125 UP						
	X	X	X	X		Wing - LH	25S-7D5057-01	SMR5057-01	\$5126	Please call
	X	X	X	X		Wing – RH	25S-7D5057-02	SMR5057-02	\$5126	Please call
		X	X	X		Horiz Stab – LH	25S-7D5057-07	SMR5057-07	\$2673	Please call
		X	X	X		Horiz Stab – RH	25S-7D5057-08	SMR5057-08	\$2673	Please call
X	X	X	X	X		Vertical Fin	25S-7D5057-09	SMR5057-09	\$2775	Please call
			X*	X*		Wing – LH	25S-7D5057-11	SMR5057-11	\$5689	Please call
			X*	X*		Wing – RH	25S-7D5057-12	SMR5057-12	\$5689	Please call
			X**	X**		Inbd – LH	25S-7D5057-13	SMR5057-13	\$2210	Please call
			X**	X**		Outbd – RH	25S-7D5057-14	SMR5057-14	\$2210	Please call

* Wet Wing **Check Aircraft 58/58G S/N TH1472 – TH1475, TH1477 – TH1486, TH1488, TH1489, TH1498 and UP

Beech (Raytheon) 60 Duke

60	A60	B60				Location:	Goodrich P/N:	SMR P/N:	List:	Your Cost:
		P-123 – P-251	P-123 – P-252	P-123 – P-253						
X	X	X				Horiz Stab – LH	23S-2124-2-1	SMR2124-2-1	\$4516	Please call
X	X	X				Horiz Stab – RH	23S-2124-2-2	SMR2124-2-2	\$4516	Please call
X	X	X		X		Vertical Fin	23S-2124-3-1	SMR2124-3-1	\$2863	Please call
X						Nac – Tip – LH	23S-2124-4-1	SMR2124-4-1	\$5358	Please call
X						Nac – Tip – RH	23S-2124-4-2	SMR2124-4-2	\$5358	Please call
X	X		X			Nac – Tip – LH	23S-2124-5-1	SMR2124-5-1	\$5973	Please call
X	X		X			Nac – Tip – RH	23S-2124-5-2	SMR2124-5-2	\$5358	Please call

FAA requires de-ice boots to be replaced in pairs for all Ice Shield 2 part numbers (replacement option for Goodrich tube-type de-icers).

Beech (Raytheon) 60 Duke

B60				Location:	Goodrich P/N:	SMR P/N:	List:	Your Cost:
P-247 – P-252	P-253 – P-347, P-349 – P-364	P-348, P-365 Up						
	X			Wing – LH	25S-7D5057-01	SMR5057-01	\$5126	Please call
	X			Wing – RH	25S-7D5057-02	SMR5057-02	\$5126	Please call
X	X	X		Horiz Stab – RH	25S-7D5057-05	SMR5057-05	\$3696	Please call
X	X	X		Horiz Stab – LH	25S-7D5057-06	SMR5057-06	\$3696	Please call
X	X	X		Vertical Fin	25S-7D5057-10	SMR5057-10	\$2480	Please call
				Wing – LH	25S-7D5057-11	SMR5057-11	\$5689	Please call
				Wing – RH	25S-7D5057-12	SMR5057-12	\$5689	Please call

Beech (Raytheon) Queen Air 65 Series

A65	A65-80	65-A80	65-A80-800	65-B80	65-88	Location:	Goodrich P/N:	SMR P/N:	List:	Your Cost:
X		X	X	X		Horiz Stab	23S-2014-9-1	SMR2014-9-1	\$2698	Please call
X				X		Vertical Fin	23S-2014-10-1	SMR2014-10-1	\$2698	Please call
	X	X	X	X	X	Brk – Light – LH	23S-2014-11-1	SMR2014-11-1	\$5814	Please call
	X	X	X	X	X	Brk – Light – RH	23S-2014-11-2	SMR2014-11-2	\$5814	Please call
				X		Light – Tip – LH	23S-2014-15-1	SMR2014-15-1	\$2969	Please call
				X		Light – Tip – RH	23S-2014-15-2	SMR2014-15-2	\$2969	Please call

FAA requires de-ice boots to be replaced in pairs for all Ice Shield 2 part numbers (replacement option for Goodrich tube-type de-icers).

Beech (Raytheon) Queen Air 65 Series

65-90	65-A90	65-A90-1	65-A90-2	65-A90-3	65-A90-4	Location:	Goodrich P/N:	SMR P/N:	List:	Your Cost:
X	X					Engine Inlet	5E1319	SMR1319	\$1134	Please call
X	X	X	X	X	X	Horiz Stab	23S-2014-9-1	SMR2014-9-1	\$2698	Please call
X	X	X	X	X	X	Vertical Fin	23S-2014-10-1	SMR2014-10-1	\$2698	Please call
X	X	X	X	X	X	Brk – Light – LH	23S-2014-11-1	SMR2014-11-1	\$5814	Please call
X	X	X	X	X	X	Brk – Light – RH	23S-2014-11-2	SMR2014-11-2	\$5814	Please call
			X	X		Brk – Light – LH	23S-2014-13-1	SMR2014-13-1	\$6765	Please call
			X	X		Brk – Light – RH	23S-2014-13-2	SMR2014-13-2	\$6327	Please call
	X					Light – Tip – LH	23S-2014-15-1	SMR2014-15-1	\$2969	Please call
	X					Light – Tip – RH	23S-2014-15-2	SMR2014-15-2	\$2969	Please call
					X	Light – Tip – LH	23S-2014-22-1	SMR2014-22-1	\$3178	Please call
					X	Light – Tip – RH	23S-2014-22-2	SMR2014-22-2	\$3178	Please call
					X	Light – Tip – LH	23S-2014-23-1	SMR2014-23-1	\$2859	Please call
					X	Light – Tip – RH	23S-2014-23-2	SMR2014-23-2	\$2859	Please call

FAA requires de-ice boots to be replaced in pairs for all Ice Shield 2 part numbers (replacement option for Goodrich tube-type de-icers).

Beech (Raytheon) Queen Air/King Air 70, 90

70	B90	C90	E90	Location:	Goodrich P/N:	SMR P/N:	List:	Your Cost:
	X	X	X	Engine Inlet	5E1319	SMR1319	\$1134	Please call
X	X		X	Horiz Stab	23S-2014-9-1	SMR2014-9-1	\$2698	Please call
X	X		X	Vertical Fin	23S-2014-10-1	SMR2014-10-1	\$2698	Please call
X	X			Brk – Light – LH	23S-2014-11-1	SMR2014-11-1	\$5814	Please call
X	X			Brk – Light – RH	23S-2014-11-2	SMR2014-11-2	\$5814	Please call
	X		X	Light – Tip – LH	23S-2014-15-1	SMR2014-15-1	\$2969	Please call
	X		X	Light – Tip – RH	23S-2014-15-2	SMR2014-15-2	\$2969	Please call

*Check aircraft to identify correct boots needed

FAA requires de-ice boots to be replaced in pairs for all Ice Shield 2 part numbers (replacement option for Goodrich tube-type de-icers).

Beech (Raytheon) King Air C90 Series

C90/C90A C90GT	C90/C90A/C90GT C90GTi	C90GT/C90GTi	Location:	Goodrich P/N:	SMR P/N:	List:	Your Cost:	
LJ-640 – LH-658	LJ-659	LJ-660 – LH-1786	LJ-1787 Up					
X	X	X	Wing – LH	25S-7D5064-03	SMR5064-03	\$5257	Please call	
X	X	X	Wing – RH	25S-7D5064-04	SMR5064-04	\$5257	Please call	
	X	X	Horiz Stab	25S-7D5064-05	SMR5064-05	\$3003	Please call	
		X	Vertical Fin	25S-7D5064-10	SMR5064-10	\$2673	Please call	
			X	Wing – LH	25S-7D5064-25	SMR5064-25	\$5344	Please call
			X	Wing – RH	25S-7D5064-26	SMR5064-26	\$5344	Please call

Beech (Raytheon) King Air 90 and 99 Series

E90	F90	F90A	H90	99,99A,A99, A99A,B99	C99	Location:	Goodrich P/N:	SMR P/N:	List:	Your Cost:
LW 120 Up										
				X		Engine Inlet	5E1319	SMR1319	\$1134	Please call
		X				Outbd Wing – LH	25S-7D5041-01	SMR5041-01	\$5167	Please call
		X				Outbd Wing – RH	25S-7D5041-02	SMR5041-02	\$5167	Please call
	X					Wing – LH	25S-7D5064-01	SMR5064-01	\$4755	Please call
	X					Wing – RH	25S-7D5064-02	SMR5064-02	\$4755	Please call
X			X			Wing – LH	25S-7D5064-03	SMR5064-03	\$5257	Please call
X			X			Wing – RH	25S-7D5064-04	SMR5064-04	\$5257	Please call
X			X			Horiz Stab	25S-7D5064-05	SMR5064-05	\$3003	Please call
				X	X	Horiz Stab	25S-7D5064-07	SMR5064-07	\$4116	Please call
X			X			Vertical Fin	25S-7D5064-10	SMR5064-10	\$2673	Please call
	X					Horiz Stab – LH	25S-7D5064-17	SMR5064-17	\$4466	Please call
	X					Horiz Stab – RH	25S-7D5064-18	SMR5064-18	\$4466	Please call
					X	Wing – LH	25S-7D5064-21	SMR5064-21	\$5861	Please call
					X	Wing – RH	25S-7D5064-22	SMR5064-22	\$5861	Please call
				X	X	Vertical Fin	25S-7D5064-23	SMR5064-23	\$2954	Please call

*All S/Ns

Beech (Raytheon) Baron 95 Series

95	B95	B95A,D95A,E95	Location:	Goodrich P/N:	SMR P/N:	List:	Your Cost:
X	X		Light – Tip – LH	23S-2004-2-1	SMR2004-2-1	\$4502	Please call
X	X		Light – Tip – RH	23S-2004-2-2	SMR2004-2-2	\$3489	Please call
	X	X	Horiz Stab – LH	23S-2004-5-1	SMR2004-5-1	\$3093	Please call
	X	X	Horiz Stab – RH	23S-2004-5-2	SMR2004-5-2	\$3093	Please call

FAA requires de-ice boots to be replaced in pairs for all Ice Shield 2 part numbers (replacement option for Goodrich tube-type de-icers).

Beech (Raytheon) King Air 99 and 100

99	99A	A99, A99A, B99	100	A100	Location:	Goodrich P/N:	SMR P/N:	List:	Your Cost:
			B2-89, B93	B1, B91, B92, B94-234					
X	X	X	X	X	Engine Inlet	5E1319	SMR1319	\$1134	Please call
				X	Brk – Tip – LH	23S-2014-21-1	SMR2014-21-1	\$6285	Please call
				X	Brk – Tip – RH	23S-2014-21-2	SMR2014-21-2	\$6285	Please call
			X	X	Horiz Stab	23S-2128-5-1	SMR2128-5-1	\$4385	Please call
			X	X	Vertical Fin	23S-2128-6-1	SMR2128-6-1	\$4385	Please call

*Check aircraft to identify correct boots needed

FAA requires de-ice boots to be replaced in pairs for all Ice Shield 2 part numbers (replacement option for Goodrich tube-type de-icers).

Beech (Raytheon) King Air 100 Series

100	A100	A100A	A100C	B100	Location:	Goodrich P/N:	SMR P/N:	List:	Your Cost:
	B235 Up								
X	*X	X	X		Engine Inlet	5E1319	SMR1319	\$1134	Please call
	*X			X	Wing – LH	25S-7D5064-01	SMR5064-01	\$4755	Please call
	*X			X	Wing – RH	25S-7D5064-02	SMR5064-02	\$4755	Please call
X	*X			X	Horiz Stab	25S-7D5064-07	SMR5064-07	\$4116	Please call
X	*X			X	Vertical Fin	25S-7D5064-23	SMR5064-23	\$2954	Please call

*All S/Ns

Beech (Raytheon) King Air 200 Series

200	A200	B200	200C,200CT,200T B200C,B200CT, B200T	Raisbeck Conv	Location:	Goodrich P/N:	SMR P/N:	List:	Your Cost:
X	X	X	X	X	OutbdWing – LH	25S-7D5041-01	SMR5041-01	\$5167	Please call
X	X	X	X	X	OutbdWing – RH	25S-7D5041-02	SMR5041-02	\$5167	Please call
X	X	X	X	X	Horiz Stab	25S-7D5041-05	SMR5041-05	\$3662	Please call
X	X	X	X		InbdWing – LH	25S-7D5041-07	SMR5041-07	\$2611	Please call
X	X	X	X		InbdWing – RH	25S-7D5041-08	SMR5041-08	\$2611	Please call
				X	InbdWing – LH	25S-7D5041-13	SMR5041-13	\$2512	Please call
				X	InbdWing – RH	25S-7D5041-14	SMR5041-14	\$2512	Please call

Beech (Raytheon) King Air 300 Series

300	300LW	B300	B300C	Location:	Goodrich P/N:	SMR P/N:	List:	Your Cost:
X	X	X	X	InbdWing – LH	25S-7D5041-09	SMR5041-09	\$2555	Please call
X	X	X	X	InbdWing – RH	25S-7D5041-10	SMR5041-10	\$2555	Please call
X	X			OutbdWing – LH	25S-7D5041-11	SMR5041-11	\$4995	Please call
X	X			OutbdWing – RH	25S-7D5041-12	SMR5041-12	\$4940	Please call
		X	X	OutbdWing – LH	25S-7D5041-17	SMR5041-17	\$4810	Please call
		X	X	OutbdWing – RH	25S-7D5041-18	SMR5041-18	\$4810	Please call
X	X	X	X	Horiz Stab – LH	25S-7D5064-17	SMR5064-17	\$4466	Please call
X	X	X	X	Horiz Stab – RH	25S-7D5064-18	SMR5064-18	\$4466	Please call

Beech (Raytheon) 1900

1900	1900C UB-1 & Up	1900C UC-1 & Up	1900C UD-1 & Up	1900D	Location:	Goodrich P/N:	SMR P/N:	List:	Your Cost:
X	X	X	X		Fus – Nac – LH	29S-7D5137-01	SMR5137-01	\$2977	Please call
X	X	X	X		Fus – Nac – RH	29S-7D5137-02	SMR5137-02	\$2977	Please call
X	X				Nac – Brk – LH	29S-7D5137-03	SMR5137-03	\$2476	Please call
X	X				Nac – Brk – RH	29S-7D5137-04	SMR5137-04	\$2476	Please call
X	X				Brk – Tip – RH	29S-7D5137-06	SMR5137-06	\$5720	Please call
X	X	X	X		Horiz Stab – LH	29S-7D5137-07	SMR5137-07	\$3295	Please call
X	X	X	X		Horiz Stab – RH	29S-7D5137-08	SMR5137-08	\$3295	Please call
X	X				Brk – Tip – LH	29S-7D5137-13	SMR5137-13	\$5720	Please call
X	X	X	X	X	Stabilon – LH	29S-7D5137-15	SMR5137-15	\$3636	Please call
X	X	X	X	X	Stabilon – RH	29S-7D5137-16	SMR5137-16	\$3636	Please call
		X	X		Nac – Brk – LH	29S-7D5137-17	SMR5137-17	\$2886	Please call
		X	X		Nac – Brk – RH	29S-7D5137-18	SMR5137-18	\$2886	Please call
		X	X		Brk – Tip – LH	29S-7D5137-19	SMR5137-19	\$6123	Please call
		X	X		Brk – Tip – RH	29S-7D5137-20	SMR5137-20	\$6123	Please call
				X	Fus - Nac – LH	29S-7D5137-21	SMR5137-21	\$2519	Please call
				X	Fus - Nac – RH	29S-7D5137-22	SMR5137-22	\$2519	Please call
				X	Nac - Brk – LH	29S-7D5137-23	SMR5137-23	\$1776	Please call
				X	Nac - Brk – RH	29S-7D5137-24	SMR5137-24	\$1776	Please call
				X	Horiz Stab – LH	29S-7D5137-25	SMR5137-25	\$2817	Please call
				X	Horiz Stab – RH	29S-7D5137-26	SMR5137-26	\$2817	Please call
				X	Brk - Tip – LH	29S-7D5137-77	SMR5137-77	\$7187	Please call
				X	Brk - Tip – RH	29S-7D5137-78	SMR5137-78	\$7187	Please call
				X	Taillet – LH	29S-4D5201-05	SMR5201-05	\$2206	Please call
				X	Taillet – RH	29S-4D5201-06	SMR5201-06	\$2206	Please call

Cessna 208 Caravan

208	208A	208B	Location:	Goodrich P/N:	SMR P/N:	List:	Your Cost:
X	X	X	Cargo Box	29S-7D5175-15	SMR5175-15	\$2477	Please call
X	X	X	MLG Fairing	35-7D5175-21	SMR5175-21	\$940	Please call
X	X	X	MLG Fairing	35-7D5175-22	SMR5175-22	\$940	Please call
X	X	X	InbdWing – LH	25S-7D5175-01 29S-7D5175-23	SMR5175-23	\$5876	Please call
X	X	X	InbdWing – RH	25S-7D5175-02 29S-7D5175-24	SMR5175-24	\$5876	Please call
X	X	X	OutbdWing – LH	25S-7D5175-11 29S-7D5175-25	SMR5175-25	\$5058	Please call
X	X	X	OutbdWing – RH	25S-7D5175-12 29S-7D5175-26	SMR5175-26	\$5058	Please call
X	X	X	Horiz Stab	25S-7D5175-05 29S-7D5175-27	SMR5175-27	\$3642	Please call
X	X	X	Vertical Fin	25S-7D5175-07 29S-7D5175-29	SMR5175-29	\$2567	Please call
X	X	X	Strut	25S-7D5175-09 29S-7D5175-31	SMR5175-31	\$3080	Please call

Cessna 210 Centurion

210,210A,210B 210C,210D 210E	210F,210G, 210H 210J,210K 210L	210M	T210F,T210G T210H,T210J T210K,T210L	Location:	Goodrich P/N:	SMR P/N:	List:	Your Cost:
		Up to 62868						
X	X	X	X	Horiz Stab	23S-2038-3-1	SMR2038-3-1	\$2490	Please call
X	X	X	X	Wing – LH	23S-2038-5-1	SMR2038-5-2	\$4565	Please call
X	X	X	X	Wing – RH	23S-2038-5-2	SMR2038-5-2	\$4988	Please call
X	X	X	X	Wing – LH	23S-2038-6-1	SMR2038-6-1	\$4741	Please call

FAA requires de-ice boots to be replaced in pairs for all Ice Shield 2 part numbers (replacement option for Goodrich tube-type de-icers).

Cessna 210 Centurion

T210M Up to 62868	P210N 1 to 120	Location:	Goodrich P/N:	SMR P/N:	List:	Your Cost:
X	X	Horiz Stab	23S-2038-3-1	SMR2038-3-1	\$2490	Please call
X	X	Wing – LH	23S-2038-5-1	SMR2038-5-2	\$4565	Please call
X	X	Wing – RH	23S-2038-5-2	SMR2038-5-2	\$4988	Please call
X	X	Wing – LH	23S-2038-6-1	SMR2038-6-1	\$4741	Please call

FAA requires de-ice boots to be replaced in pairs for all Ice Shield 2 part numbers (replacement option for Goodrich tube-type de-icers).

Cessna 210 Centurion

210N	P210N 121-834	T210N	T210N 62955-64722	Location:	Goodrich P/N:	SMR P/N:	List:	Your Cost:
X	X		X	Wing – LH	25S-5D5101-01	SMR5101-01	\$4176	Please call
X	X		X	Wing – RH	25S-5D5101-02	SMR5101-02	\$4135	Please call
X	X	X	X*	Horiz Stab – LH	25S-5D5101-03	SMR5101-03	\$2241	Please call
X	X	X	X*	Horiz Stab – RH	25S-5D5101-04	SMR5101-04	\$2241	Please call
X	X	X	X*	Vertical Fin	25S-5D5101-05	SMR5101-05	\$1775	Please call

*No S/N break

Cessna 210 Centurion

T210R	210R	P210R	Location:	Goodrich P/N:	SMR P/N:	List:	Your Cost:
X	X	X	Wing – LH	25S-5D5170-01	SMR5170-01	\$4227	Please call
X	X	X	Wing – RH	25S-5D5170-02	SMR5170-02	\$4149	Please call
X	X	X	Horiz Stab – LH	25S-5D5170-03	SMR5170-03	\$2532	Please call
X	X	X	Horiz Stab – RH	25S-5D5170-04	SMR5170-04	\$2532	Please call
X	X	X	Vertical Fin	25S-5D5101-05	SMR5101-05	\$1775	Please call
X	X	X	Wing Tip – LH	25S-5D5170-07	SMR5170-07	\$1297	Please call
X	X	X	Wing Tip – RH	25S-5D5170-08	SMR5170-08	\$1297	Please call

Cessna 300 Series

310A,310B,310C 310D,310E,310F 310G	310H,310I,310J 310K,310L 310N,310P	310Q,E310H E310J T310P,E310Q	310Q T310R	Location:	Goodrich P/N:	SMR P/N:	List:	Your Cost:
			1-800					
X	X	X	X	Nac – Tip – LH	23S-2010-1-1	SMR2010-1-1	\$4711	Please call
X	X	X	X	Nac-Tip-RH w/o LT	23S-2010-1-2	SMR2010-1-2	\$4368	Please call
X	X	X	X	Horiz Stab	23S-2010-2-1	SMR2010-2-1	\$3816	Please call
X	X	X	X	Nac – Tip – RH w/LT	23S-2010-3-2	SMR2010-3-2	\$4572	Please call

FAA requires de-ice boots to be replaced in pairs for all Ice Shield 2 part numbers (replacement option for Goodrich tube-type de-icers).

Cessna 300 Series

320,320A,320B	320C,320D,320E	Location:	Goodrich P/N:	SMR P/N:	List:	Your Cost:
X	X	Horiz Stab	23S-2010-2-1	SMR2010-2-1	\$3816	Please call
X	X	Nac – Tip – LH	23S-2010-6-1	SMR2010-6-1	\$4768	Please call
X	X	Nac – Tip – RH	23S-2010-6-2	SMR2010-6-2	\$4425	Please call

FAA requires de-ice boots to be replaced in pairs for all Ice Shield 2 part numbers (replacement option for Goodrich tube-type de-icers).

Cessna 300 Series

320F	340	Location:	Goodrich P/N:	SMR P/N:	List:	Your Cost:
	X	Nac - Tip - LH	23S-2010-1-1	SMR2010-1-1	\$4711	Please call
	X	Nac - Tip - RH	23S-2010-1-2	SMR2010-1-2	\$4368	Please call
X	X	Horiz Stab	23S-2010-2-1	SMR2010-2-1	\$3816	Please call
	X	Vertical Fin	23S-2010-5-1	SMR2010-5-1	\$2964	Please call
X		Nac - Tip - LH	23S-2010-6-1	SMR5010-6-1	\$4768	Please call
X		Nac - Tip - RH	23S-2010-6-2	SMR5010-6-2	\$4425	Please call

FAA requires de-ice boots to be replaced in pairs for all Ice Shield 2 part numbers (replacement option for Goodrich tube-type de-icers).

Cessna 300 Series

310R	335	340A	Location:	Goodrich P/N:	SMR P/N:	List:	Your Cost:
X	X	X	Nac - Tip - LH	27S-7D5070-03	SMR5070-03	\$4376	Please call
X	X	X	Nac - Tip - RH	27S-7D5070-04	SMR5070-04	\$4376	Please call
X	X	X	Horiz Stab	27S-7D5070-11	SMR5070-11	\$2789	Please call
X	X	X	Vertical Fin	27S-7D5070-13	SMR5070-13	\$2673	Please call
X			Fus - Nac - LH	27S-7D5070-29	SMR5070-29	\$2109	Please call
X			Fus - Nac - RH	27S-7D5070-30	SMR5070-30	\$2109	Please call
		X	Fus - Nac - LH	27S-7D5070-31	SMR5070-31	\$2055	Please call
		X	Fus - Nac - RH	27S-7D5070-32	SMR5070-32	\$2055	Please call
	X		Fus - Nac - LH	27S-7D5070-51	SMR5070-51	\$2391	Please call
	X		Fus - Nac - RH	27S-7D5070-52	SMR5070-52	\$2391	Please call

Cessna T303 Crusader

T303	Location:	Goodrich P/N:	SMR P/N:	List:	Your Cost:
X	InBd Wing - LH	25S-5D5124-01	SMR5124-01	\$2712	Please call
X	InBd Wing - RH	25S-5D5124-02	SMR5124-02	\$2712	Please call
X	OutBd Wing - LH	25S-5D5124-03	SMR5124-03	\$3989	Please call
X	OutBd Wing - RH	25S-5D5124-04	SMR5124-04	\$3989	Please call
X	Horiz Stab - LH	25S-5D5124-05	SMR5124-05	\$2698	Please call
X	Horiz Stab - RH	25S-5D5124-06	SMR5124-06	\$2698	Please call
X	Vertical Fin	25S-5D5124-07	SMR5124-07	\$2415	Please call

Cessna 337 Skymaster

337F T337F	337G	T337G	337H P337H	Location:	Goodrich P/N:	SMR P/N:	List:	Your Cost:
X	*X	**X		Fus - Tip - LH	25S-5D5053-01	SMR5053-01	\$7639	Please call
X	X	X	X	Fus - Tip - RH	25S-5D5053-02	SMR5053-02	\$7639	Please call
X	X	X	X	Horiz Stab	25S-5D5053-03	SMR5053-03	\$4413	Please call

*SMR5053-01 available on 337G up to S/N 3701763, **SMR5053-01 available on T337G up to S/N P3370259

Cessna 337 Skymaster

T337H	T337-SP	Location:	Goodrich P/N:	SMR P/N:	List:	Your Cost:
X	X	Fus - Tip - RH	25S-5D5053-02	SMR5053-02	\$7639	Please call
X	X	Horiz Stab	25S-5D5053-03	SMR5053-03	\$4413	Please call

Cessna 400 Series

401,401A,401B	402,402A	402B 1-800	Location:	Goodrich P/N:	SMR P/N:	List:	Your Cost:
X	X	X	Nac - Tip - LH	23S-2010-6-1	SMR2010-6-1	\$4768	Please call
X	X	X	Nac - Tip - RH	23S-2010-6-2	SMR2010-6-2	\$4425	Please call
X	X	X	Horiz Stab	23S-2074-2-1	SMR2074-2-1	\$2885	Please call
X	X	X	Vertical Fin	23S-2074-3-1	SMR2074-3-1	\$3923	Please call

FAA requires de-ice boots to be replaced in pairs for all Ice Shield 2 part numbers (replacement option for Goodrich tube-type de-icers).

Cessna 400 (402B & 402C)

402B	402C w/Lights	402C w/o Lights	Location:	Goodrich P/N:	SMR P/N:	List:	Your Cost:
X			Nac - Tip – LH	27S-7D5070-03	SMR5070-03	\$4376	Please call
X			Nac - Tip – RH	27S-7D5070-04	SMR5070-04	\$4376	Please call
X			Fus - Nac – LH	27S-7D5070-05	SMR5070-05	\$2363	Please call
X			Fus - Nac – RH	27S-7D5070-06	SMR5070-06	\$2363	Please call
X	X	X	Horiz Stab	27S-7D5070-11	SMR5070-11	\$2789	Please call
X			Vertical Fin	27S-7D5070-13	SMR5070-13	\$2673	Please call
	X	X	Vertical Fin	27S-7D5070-14	SMR5070-14	\$2673	Please call
		X	Nac - Tip – LH	27S-7D5070-37	SMR5070-37	\$5167	Please call
		X	Nac - Tip – RH	27S-7D5070-38	SMR5070-38	\$4741	Please call
	X	X	Fus - Nac – LH	27S-7D5070-41	SMR5070-41	\$2801	Please call
	X	X	Fus - Nac – RH	27S-7D5070-42	SMR5070-42	\$2801	Please call
	X		Nac - Tip – LH	27S-7D5070-59	SMR5070-59	\$4418	Please call
	X		Nac - Tip – RH	27S-7D5070-60	SMR5070-60	\$4418	Please call

Cessna 400 (404)

404 0001 to 0600	404 0601 & Up	Location:	Goodrich P/N:	SMR P/N:	List:	Your Cost:
X	X	Fus - Nac – LH	27S-7D5070-17	SMR5070-17	\$1992	Please call
X	X	Fus - Nac – RH	27S-7D5070-18	SMR5070-18	\$1992	Please call
X	X	Horiz Stab	27S-7D5070-21	SMR5070-21	\$2817	Please call
X	X	Vertical Fin	27S-7D5070-23	SMR5070-23	\$2569	Please call
X	X	Fairing – LH	27S-7D5070-33	SMR5070-33	\$3635	Please call
X	X	Fairing – RH	27S-7D5070-34	SMR5070-34	\$3635	Please call
X		Nac - Tip – RH	27S-7D5070-36	SMR5070-36	\$4642	Please call
X		Nac - Tip – LH	27S-7D5070-39	SMR5070-39	\$4741	Please call
	X	Nac - Tip – LH	27S-7D5070-45	SMR5070-45	\$5352	Please call
	X	Nac - Tip – RH	27S-7D5070-46	SMR5070-46	\$5503	Please call

Cessna 400 Series

411,411A	414 1-600	421,421A,421B	Location:	Goodrich P/N:	SMR P/N:	List:	Your Cost:
	X		Nac – Tip – LH	23S-2010-6-1	SMR2010-6-1	\$4768	Please call
	X		Nac – Tip – RH	23S-2010-6-2	SMR2010-6-2	\$4425	Please call
X		X	Nac – Tip – LH	23S-2074-1-1	SMR2074-1-1	\$3739	Please call
X		X	Nac – Tip – RH	23S-2074-1-2	SMR2074-1-2	\$4008	Please call
X	X	X	Horiz Stab	23S-2074-2-1	SMR2074-2-1	\$2885	Please call
X	X	X	Vertical Fin	23S-2074-3-1	SMR2074-3-1	\$3923	Please call

FAA requires de-ice boots to be replaced in pairs for all Ice Shield 2 part numbers (replacement option for Goodrich tube-type de-icers).

Cessna 400

414	414A w/Lights	414A w/o Lights	421B	421C w/Lights	421C w/o Lights	Location:	Goodrich P/N:	SMR P/N:	List:	Your Cost:
X						Fus – Nac – LH	27S-7D5070-01	SMR5070-01	\$2254	Please call
X						Fus – Nac – RH	27S-7D5070-02	SMR5070-02	\$2254	Please call
X						Nac – Tip – LH	27S-7D5070-03	SMR5070-03	\$4376	Please call
X						Nac – Tip – RH	27S-7D5070-04	SMR5070-04	\$4376	Please call
	X	X	X	X	X	Fus – Nac – LH	27S-7D5070-07	SMR5070-07	\$2254	Please call
	X	X	X	X	X	Fus – Nac – RH	27S-7D5070-08	SMR5070-08	\$2254	Please call
			X			Nac – Tip – LH	27S-7D5070-09	SMR5070-09	\$3909	Please call
			X			Nac – Tip – RH	27S-7D5070-10	SMR5070-10	\$3909	Please call
X	X	X	X	X	X	Horiz Stab	27S-7D5070-11	SMR5070-11	\$2789	Please call
X			X			Vertical Fin	27S-7D5070-13	SMR5070-13	\$2673	Please call
	X	X		X	X	Vertical Fin	27S-7D5070-14	SMR5070-14	\$2673	Please call
					X	Nac – Tip – LH	27S-7D5070-15	SMR5070-15	\$4967	Please call
					X	Nac – Tip – RH	27S-7D5070-16	SMR5070-16	\$4967	Please call
		X				Nac – Tip – LH	27S-7D5070-37	SMR5070-37	\$5167	Please call
		X				Nac – Tip – RH	27S-7D5070-38	SMR5070-38	\$4741	Please call
				X		Nac – Tip – LH	27S-7D5070-57	SMR5070-57	\$3937	Please call
				X		Nac – Tip – RH	27S-7D5070-58	SMR5070-58	\$3937	Please call
	X					Nac – Tip – LH	27S-7D5070-59	SMR5070-59	\$4418	Please call
	X					Nac – Tip – RH	27S-7D5070-60	SMR5070-60	\$4418	Please call

Cessna 400 (425)

425 to 190	425 191 & Up	Location:	Goodrich P/N:	SMR P/N:	List:	Your Cost:
X	X	Vertical Fin	27S-7D5070-14	SMR5070-14	\$2673	Please call
X	X	Horiz Stab	27S-7D5070-21	SMR5070-21	\$2817	Please call
X		Nac - Tip – LH	27S-7D5070-49	SMR5070-49	\$5874	Please call
X		Nac - Tip – RH	27S-7D5070-50	SMR5070-50	\$5874	Please call
X	X	Fus - Nac – LH	27S-7D5070-53	SMR5070-53	\$3188	Please call
X	X	Fus - Nac – RH	27S-7D5070-54	SMR5070-54	\$3188	Please call
	X	Nac - Tip – LH	27S-7D5070-55	SMR5070-55	\$4328	Please call
	X	Nac - Tip – RH	27S-7D5070-56	SMR5070-56	\$4328	Please call

Cessna 400 (406 & 441)

406	441 1-102	441 103 & Up	Location:	Goodrich P/N:	SMR P/N:	List:	Your Cost:
	X	X	Horiz Stab	27S-7D5070-21	SMR5070-21	\$2817	Please call
	X	X	Vertical Fin	27S-7D5070-23	SMR5070-23	\$2569	Please call
X	X	X	Fus - Nac – LH	27S-7D5109-01	SMR5109-01	\$3789	Please call
X	X	X	Fus - Nac – RH	27S-7D5109-02	SMR5109-02	\$3789	Please call
	X		Nac - Tip – LH	27S-7D5109-03	SMR5109-03	\$6567	Please call
	X		Nac - Tip – RH	27S-7D5109-04	SMR5109-04	\$6567	Please call
	X	X	Fus – Nac Ext	27S-7D5109-05	SMR5109-05	\$2492	Please call
		X	Nac - Tip – LH	27S-7D5109-07	SMR5109-07	\$6965	Please call
		X	Nac - Tip – RH	27S-7D5109-08	SMR5109-08	\$6965	Please call

Cessna – 500 Citation

500 0001-0349	500 0350 & up	500 STC SA645NW	Location:	Goodrich P/N:	SMR P/N:	List:	Your Cost:
X			Wing – LH	25S-7D5059-01	SMR5059-01	\$4973	Please call
X			Wing – RH	25S-7D5059-02	SMR5059-02	\$4973	Please call
X*	X*	X*	Horiz Stab	25S-7D5059-03	SMR5059-03	\$3050	Please call
X	X	X	Vertical Fin	25S-7D5059-05	SMR5059-05	\$2672	Please call
	X		Wing – LH	25S-7D5059-07	SMR5059-07	\$5856	Please call
	X		Wing – RH	25S-7D5059-08	SMR5059-08	\$5856	Please call
		X	Wing – LH	25S-7D5059-11	SMR5059-11	\$4718	Please call
		X	Wing – RH	25S-7D5059-12	SMR5059-12	\$4718	Please call
X*	X*	X*	Horiz Stab	25S-7D5059-13	SMR5059-13	\$3017	Please call

*SMR5059-03 and SMR5059-13 are interchangeable

Cessna – 501, 550 and 551 Citation

501	550	551	Location:	Goodrich P/N:	SMR P/N:	List:	Your Cost:
X	X*	X	Horiz Stab	25S-7D5059-03	SMR5059-03	\$3050	Please call
X	X	X	Vertical Fin	25S-7D5059-05	SMR5059-05	\$2672	Please call
X			Wing – LH	25S-7D5059-07	SMR5059-07	\$5856	Please call
X			Wing – RH	25S-7D5059-08	SMR5059-08	\$5856	Please call
		X	Wing – LH	25S-7D5059-09	SMR5059-09	\$5946	Please call
		X	Wing – RH	25S-7D5059-10	SMR5059-10	\$5946	Please call
	X		Wing – LH	25S-7D5059-11	SMR5059-11	\$4718	Please call
	X		Wing – RH	25S-7D5059-12	SMR5059-12	\$4718	Please call
	X*		Horiz Stab	25S-7D5059-13	SMR5059-13	\$3017	Please call

*SMR5059-03 and SMR5059-13 are interchangeable

Cessna – 525 Citation

525	Location:	Goodrich P/N:	SMR P/N:	List:	Your Cost:
X	Horiz Stab	25S-4D5244-01	SMR5244-01	\$3606	Please call
X	Horiz Stab	25S-4D5244-02	SMR5244-02	\$3606	Please call

Cessna – 560 Citation

560	560 XL	Location:	Goodrich P/N:	SMR P/N:	List:	Your Cost:
X		Wing – LH	35-5D5230-01	SMR5230-01	\$8951	Please call
X		Wing – RH	35-5D5230-02	SMR5230-02	\$8951	Please call
X		Horiz Stab LH	39S-5D5225-05	SMR5225-05	\$5410	Please call
X		Horiz Stab RH	39S-5D5225-06	SMR5225-06	\$5410	Please call
	X	Horiz Stab LH	29S4D5280-01	SMR5280-01	\$5410	Please call
	X	Horiz Stab RH	29S4D5280-02	SMR5280-02	\$5410	Please call

DeHavilland DHC-6 Twin Otter

DHC6 All	DHC6-100	DHC6-200	DHC6-300	Location:	Goodrich P/N:	SMR P/N:	List:	Your Cost:
X	X	X	X	Engine Inlet	5E1346	SMR1346	\$1702	Please call
X	X	X	X	Wing – LH	23S-2099-1-1	SMR2099-1-1	\$5990	Please call
X	X	X	X	Wing – RH	23S-2099-1-2	SMR2099-1-2	\$5990	Please call
X	X	X	X	Horiz Stab – LH	23S-2099-50-1	SMR2099-50-1	\$3860	Please call
X	X	X	X	Horiz Stab – RH	23S-2099-50-2	SMR2099-50-2	\$3860	Please call

FAA requires de-ice boots to be replaced in pairs for all Ice Shield 2 part numbers (replacement option for Goodrich tube-type de-icers).

Dornier DO-228

100,101	200,201	202,212	Location:	Goodrich P/N:	SMR P/N:	List:	Your Cost:
X	X	X	Brk – Tip – LH	29S-5D5138-03	SMR5138-03	\$3432	Please call
X	X	X	Brk – Tip – RH	29S-5D5138-04	SMR5138-04	\$3432	Please call
X	X	X	Horiz Stab – LH	30S-5D5138-05	SMR5138-05	\$7815	Please call
X	X	X	Horiz Stab – RH	30S-5D5138-06	SMR5138-06	\$7815	Please call
X	X	X	Vertical Fin	29S-5D5138-07	SMR5138-07	\$3236	Please call
X	X	X	Nac – Brk – LH	29S-5D5138-11	SMR5138-11	\$3461	Please call
X	X	X	Nac – Brk – RH	29S-5D5138-12	SMR5138-12	\$3461	Please call
X	X	X	Fus – Nac – LH	29S-5D5138-15	SMR5138-15	\$3363	Please call
X*	X*	X*	Fus – Nac – RH	29S-5D5138-16	SMR5138-16	\$3363	Please call
X**	X**	X**	Fus – Nac – RH	29S-5D5138-18	SMR5138-18	\$3075	Please call
X	X	X	Fus – Nac – LH	29S-5D5138-19	SMR5138-19	\$2796	Please call

SMR5138-15: 5.2 x 7.5 in cut-out, SMR5138-19: 5.2 x 2.0 in cut-out, *Without optional pressure refueling, **With optional pressure refueling

Embraer 110 Bandeirante

EMB - 110P1	EMB - 110P2	Location:	Goodrich P/N:	SMR P/N:	List:	Your Cost:
X	X	Engine Inlet	5E1683-1	SMR1683-1	\$1723	Please call
X	X	Fus - Nac – LH	29S-5D5158-01	SMR5158-01	\$3061	Please call
X	X	Fus - Nac – RH	29S-5D5158-02	SMR5158-02	\$3061	Please call
X	X	InBdWing – LH	29S-5D5158-03	SMR5158-03	\$3432	Please call
X	X	InBdWing – RH	29S-5D5158-04	SMR5158-04	\$3432	Please call
X	X	OutBdWing – LH	29S-5D5158-05	SMR5158-05	\$3825	Please call
X	X	OutBdWing – RH	29S-5D5158-06	SMR5158-06	\$3825	Please call
X	X	Horiz Stab – LH	29S-5D5158-07	SMR5158-07	\$4189	Please call
X	X	Horiz Stab – RH	29S-5D5158-08	SMR5158-08	\$4189	Please call
X	X	Vertical Fin	29S-5D5158-09	SMR5158-09	\$3244	Please call

Fairchild Metro / Merlin SA-226 Series

SA-226-T	SA-226-AT	SA-226-TC	Location:	Goodrich P/N:	SMR P/N:	List:	Your Cost:
X	X	X	Nac - Tip – LH	25S-5D5071-01	SMR5071-01	\$6954	Please call
X	X	X	Nac - Tip – RH	25S-5D5071-02	SMR5071-02	\$6954	Please call
X	X	X	Horiz Stab	25S-5D5071-03	SMR5071-03	\$4429	Please call

Fairchild Metro / Merlin SA-227 Series

SA-227 TT	SA-227 AC/-AT	Location:	Goodrich P/N:	SMR P/N:	List:	Your Cost:
X	X	Nac - Tip – LH	25S-5D5071-01	SMR5071-01	\$6954	Please call
X	X	Nac - Tip – RH	25S-5D5071-02	SMR5071-02	\$6954	Please call
X	X	Horiz Stab	25S-5D5071-03	SMR5071-03	\$4429	Please call
X	X	Fus - Nac – LH	25S-5D5071-13	SMR5071-13	\$2707	Please call
X	X	Fus - Nac – RH	25S-5D5071-14	SMR5071-14	\$2707	Please call
X	X	Wing Tip Ext	25S-5D5071-15	SMR5071-15	\$4416	Please call

Gulfstream Twin Commander

500*	500A,500B 500S,500U	520	Location:	Goodrich P/N:	SMR P/N:	List:	Your Cost:
X		X	Nac – Brk – LH	23S-2015-1-1	SMR2015-1-1	\$2597	Please call
X		X	Nac – Brk – RH	23S-2015-1-2	SMR2015-1-2	\$2597	Please call
		X	Brk – Tip – LH	23S-2015-2-1	SMR2015-2-1	\$2673	Please call
		X	Brk – Tip – RH	23S-2015-2-2	SMR2015-2-2	\$2673	Please call
X	X	X	Horiz Stab – LH	23S-2015-3-1	SMR2015-3-1	\$2741	Please call
X	X	X	Horiz Stab – RH	23S-2015-3-2	SMR2015-3-2	\$2741	Please call
X		X	Nac – Brk – LH	23S-2015-5-1	SMR2015-5-1	\$2467	Please call
		X	Brk – Tip – LH	23S-2015-6-1	SMR2015-6-1	\$2831	Please call
X	X		Vertical Fin	23S-2015-7-1	SMR2015-7-1	\$2398	Please call
X	X		Brk – Tip – LH	23S-2015-8-1	SMR2015-8-1	\$2940	Please call
X	X		Brk – Tip – LH	23S-2015-9-1	SMR2015-9-1	\$3015	Please call
X	X		Brk – Tip – RH	23S-2015-9-2	SMR2015-9-2	\$2900	Please call
	X		Nac – Brk – LH	23S-2015-12-1	SMR2015-12-1	\$2859	Please call
	X		Nac – Brk – RH	23S-2015-12-2	SMR2015-12-2	\$2859	Please call
	X		Nac – Brk – LH	23S-2015-13-1	SMR2015-13-1	\$3278	Please call

*Check aircraft identify correct boot needed for Brk – Tip

FAA requires de-ice boots to be replaced in pairs for all Ice Shield 2 part numbers (replacement option for Goodrich tube-type de-icers).

Gulfstream Twin Commander

560*	560A 680	560F 680F	680E	Location:	Goodrich P/N:	SMR P/N:	List:	Your Cost:
X	X		X	Nac – Brk – LH	23S-2015-1-1	SMR2015-1-1	\$2597	Please call
X	X		X	Nac – Brk – RH	23S-2015-1-2	SMR2015-1-2	\$2597	Please call
X	X			Brk – Tip – LH	23S-2015-2-1	SMR2015-2-1	\$2673	Please call
X	X			Brk – Tip – RH	23S-2015-2-2	SMR2015-2-2	\$2673	Please call
X	X	X	X	Horiz Stab – LH	23S-2015-3-1	SMR2015-3-1	\$2741	Please call
X	X	X	X	Horiz Stab – RH	23S-2015-3-2	SMR2015-3-2	\$2741	Please call
X	X		X	Nac – Brk – LH	23S-2015-5-1	SMR2015-5-1	\$2467	Please call
X	X			Brk – Tip – LH	23S-2015-6-1	SMR2015-6-1	\$2831	Please call
X	X	X	X	Vertical Fin	23S-2015-7-1	SMR2015-7-1	\$2398	Please call
X				Brk – Tip – LH	23S-2015-8-1	SMR2015-8-1	\$2940	Please call
X				Brk – Tip – LH	23S-2015-9-1	SMR2015-9-1	\$3051	Please call
X				Brk – Tip – RH	23S-2015-9-2	SMR2015-9-2	\$2900	Please call
		X		Nac – Brk – LH	23S-2015-12-1	SMR2015-12-1	\$2859	Please call
		X		Nac – Brk – RH	23S-2015-12-2	SMR2015-12-2	\$2859	Please call
		X		Nac – Brk – LH	23S-2015-13-1	SMR2015-13-1	\$3278	Please call

*Check aircraft identify correct boot needed for Brk – Tip

FAA requires de-ice boots to be replaced in pairs for all Ice Shield 2 part numbers (replacement option for Goodrich tube-type de-icers).

de-icing systems

Gulfstream Twin Commander

680F(P)	680FL 680FL(P)	680T 680V	Location:	Goodrich P/N:	SMR P/N:	List:	Your Cost:
		X	Brk – Tip – LH	23S-2015-2-1	SMR2015-2-1	\$2673	Please call
		X	Brk – Tip – RH	23S-2015-2-2	SMR2015-2-2	\$2673	Please call
		X	Brk – Tip – LH	23S-2015-6-1	SMR2015-6-1	\$2831	Please call
X	X	X	Vertical Fin	23S-2015-7-1	SMR2015-7-1	\$2398	Please call
X	X	X	Nac – Brk – LH	23S-2015-12-1	SMR2015-12-1	\$2859	Please call
X	X	X	Nac – Brk – RH	23S-2015-12-2	SMR2015-12-2	\$2859	Please call
X	X	X	Nac – Brk – LH	23S-2015-13-1	SMR2015-13-1	\$3278	Please call
	X		Horiz Stab – LH	23S-2015-14-1	SMR2015-14-1	\$2700	Please call
	X		Horiz Stab – RH	23S-2015-14-2	SMR2015-14-2	\$2700	Please call

*Check aircraft identify correct boot needed for Brk – Tip

FAA requires de-ice boots to be replaced in pairs for all Ice Shield 2 part numbers (replacement option for Goodrich tube-type de-icers).

Gulfstream Twin Commander

680W, 681	720	Location:	Goodrich P/N:	SMR P/N:	List:	Your Cost:
	X	Nac - Brk - LH	23S-2015-1-1	SMR2015-1-1	\$2597	Please call
	X	Nac - Brk - RH	23S-2015-1-2	SMR2015-1-2	\$2597	Please call
X		Brk - Tip - LH	23S-2015-2-1	SMR2015-2-1	\$2673	Please call
X		Brk - Tip - RH	23S-2015-2-2	SMR2015-2-2	\$2673	Please call
	X	Horiz Stab - LH	23S-2015-3-1	SMR2015-3-1	\$2741	Please call
	X	Horiz Stab - RH	23S-2015-3-2	SMR2015-3-2	\$2741	Please call
	X	Nac - Brk - LH	23S-2015-5-1	SMR2015-5-1	\$2467	Please call
X		Brk - Tip - LH	23S-2015-6-1	SMR2015-6-1	\$2831	Please call
X	X	Vertical Fin	23S-2015-7-1	SMR2015-7-1	\$2398	Please call
	X	Brk - Tip - LH	23S-2015-8-1	SMR2015-8-1	\$2940	Please call
	X	Brk - Tip - LH	23S-2015-9-1	SMR2015-9-1	\$3051	Please call
	X	Brk - Tip - RH	23S-2015-9-2	SMR2015-9-2	\$2900	Please call
X		Nac - Brk - LH	23S-2015-12-1	SMR2015-12-1	\$2859	Please call
X		Nac - Brk - RH	23S-2015-12-2	SMR2015-12-2	\$2859	Please call
X		Nac - Brk - LH	23S-2015-13-1	SMR2015-13-1	\$3278	Please call

*Check aircraft identify correct boot needed for Brk - Tip

FAA requires de-ice boots to be replaced in pairs for all Ice Shield 2 part numbers (replacement option for Goodrich tube-type de-icers).

Gulfstream Twin Commander

685,690 690A,690B	690C	690C	690D	Location:	Goodrich P/N:	SMR P/N:	List:	Your Cost:
	11600 & UP	11719-11999						
X				Nac - Tip - LH	25S-7D5015-01	SMR5015-01	\$3353	Please call
X				Nac - Tip - RH	25S-7D5015-02	SMR5015-02	\$3353	Please call
X	X		X	Horiz Stab - LH	25S-7D5015-03	SMR5015-03	\$2775	Please call
X	X		X	Horiz Stab - RH	25S-7D5015-04	SMR5015-04	\$2775	Please call
X	X*			Vertical Fin	25S-7D5015-05	SMR5015-05	\$2493	Please call
		X		Nac - Tip - LH	25S-7D5015-07	SMR5015-07	\$2913	Please call
		X		Nac - Tip - RH	25S-7D5015-08	SMR5015-08	\$2913	Please call
		X	X	Fus - Nac - LH	25S-7D5015-13	SMR5015-13	\$2192	Please call
		X	X	Fus - Nac - RH	25S-7D5015-14	SMR5015-14	\$2192	Please call
		X	X	Nac - Tip - LH	25S-7D5015-15	SMR5015-15	\$4088	Please call
		X	X	Nac - Tip - RH	25S-7D5015-16	SMR5015-16	\$4088	Please call
			X	Vertical Fin	25S-7D5015-21	SMR5015-21	\$2192	Please call

690C 11719-11999: Check Aircraft for appropriate selection

Gulfstream Twin Commander

695	695	695A	695A	Location:	Goodrich P/N:	SMR P/N:	List:	Your Cost:
95000-95086	95087-95999	To 96014	96015 & Up					
X*	X*		X	Horiz Stab - LH	25S-7D5015-03	SMR5015-03	\$2775	Please call
X*	X*		X	Horiz Stab - RH	25S-7D5015-04	SMR5015-04	\$2775	Please call
X				Vertical Fin	25S-7D5015-05	SMR5015-05	\$2493	Please call
X				Nac - Tip - LH	25S-7D5015-07	SMR5015-07	\$2913	Please call
X				Nac - Tip - RH	25S-7D5015-08	SMR5015-08	\$2913	Please call
	X	X	X	Fus - Nac - LH	25S-7D5015-13	SMR5015-13	\$2192	Please call
	X	X	X	Fus - Nac - RH	25S-7D5015-14	SMR5015-14	\$2192	Please call
	X	X	X	Nac - Tip - LH	25S-7D5015-15	SMR5015-15	\$4088	Please call
	X	X	X	Nac - Tip - RH	25S-7D5015-16	SMR5015-16	\$4088	Please call
		X	X	Vertical Fin	25S-7D5015-21	SMR5015-21	\$2192	Please call

*695 S/N 95000 & Up

Gulfstream Twin Commander

695B	695B	Location:	Goodrich P/N:	SMR P/N:	List:	Your Cost:
96017-96999	97000 & Up					
X	X	Fus - Nac - LH	25S-7D5015-13	SMR5015-13	\$2192	Please call
X	X	Fus - Nac - RH	25S-7D5015-14	SMR5015-14	\$2192	Please call
X	X	Nac - Tip - LH	25S-7D5015-15	SMR5015-15	\$4088	Please call
X	X	Nac - Tip - RH	25S-7D5015-16	SMR5015-16	\$4088	Please call
X		Vertical Fin	25S-7D5015-21	SMR5015-21	\$2192	Please call

Jetstream 32

Model 32	Location:	Goodrich P/N:	SMR P/N:	List:	Your Cost:
X	Nac – Light – LH	29S-7D5255-01	SMR5255-01	\$3316	Please call
X	Nac – Light – RH	29S-7D5255-02	SMR5255-02	\$3316	Please call
X	Light – Tip – LH	29S-7D5255-03	SMR5255-03	\$6084	Please call
X	Light – Tip – RH	29S-7D5255-04	SMR5255-04	\$6084	Please call
X	Horiz Stab	29S-7D5255-05	SMR5255-05	\$5065	Please call
X	Vertical Fin	29S-7D5255-07	SMR5255-07	\$3642	Please call
X	Fus - Nac – LH	29S-7D5255-09	SMR5255-09	\$3670	Please call
X	Fus - Nac – RH	29S-7D5255-10	SMR5255-10	\$3670	Please call

Mitsubishi MU-2B

MU-2B	Location:	Goodrich P/N:	SMR P/N:	List:	Your Cost:
X	Fus - Nac – LH	25S-5D5048-01 23S-2090-1-1	SMR5048-01	\$3257	Please call
X	Fus - Nac – RH	25S-5D5048-02 23S-2090-1-2	SMR5048-02	\$3257	Please call
X	Nac - Tip – LH	25S-5D5048-03 23S-2090-5-1	SMR5048-03	\$4019	Please call
X	Nac - Tip – RH	25S-5D5048-04 23S-2090-5-2	SMR5048-04	\$4019	Please call
X	Vertical Fin	25S-5D5048-07 23S-2090-4-1 23S-2090-6-1	SMR5048-07	\$3230	Please call
X	Horiz Stab – LH	25S-5D5048-09 23S-2090-3-1 23S-2090-7-1	SMR5048-09	\$3470	Please call
X	Horiz Stab – RH	25S-5D5048-10 23S-2090-3-2 23S-2090-7-2	SMR5048-10	\$3470	Please call

Pilatus PC-12

PC-12	PC-12/45	Location:	Goodrich P/N:	SMR P/N:	List:	Your Cost:
X	X	Inboard – LH	27-7D5221-09	SMR5221-09	\$4988	Please call
X	X	Inboard – RH	27-7D5221-10	SMR5221-10	\$4988	Please call
X	X	Outboard – LH	27-7D5221-11	SMR5221-11	\$6570	Please call
X	X	Outboard – RH	27-7D5221-12	SMR5221-12	\$6570	Please call
X	X	Horiz Stab – LH	27S-7D5221-13	SMR5221-13	\$3606	Please call
X	X	Horiz Stab – RH	27S-7D5221-14	SMR5221-14	\$3606	Please call

de-icing systems

Piper PA-23 Apache/Aztec Series

PA-23-235	*PA-23-250	Location:	Goodrich P/N:	SMR P/N:	List:	Your Cost:
X	X	Wing – LH	23S-2039-1-1	SMR2039-1-1	\$5681	Please call
X	X	Wing – RH	23S-2039-1-2	SMR2039-1-2	\$5260	Please call
X	X	Horiz Stab – LH	23S-2039-2-1	SMR2039-2-1	\$3178	Please call
X	X	Horiz Stab – RH	23S-2039-2-2	SMR2039-2-2	\$3178	Please call
X	X	Vertical Fin	23S-2039-3-1	SMR2039-3-1	\$3196	Please call

*Excludes S/N: 27-4773, 4817, 27-7304964, 4994, 4996, 5000, 5004, 5006, 5007, 5009, 5010, 5013, 5016, 5017, 5024, 5025

FAA requires de-ice boots to be replaced in pairs for all Ice Shield 2 part numbers (replacement option for Goodrich tube-type de-icers).

Piper PA-23-250 Aztec Series

PA-23-250	PA-23-E250	Location:	Goodrich P/N:	SMR P/N:	List:	Your Cost:
X	X	Wing – LH	25S-7D5063-01	SMR5063-01	\$4995	Please call
X	X	Wing – RH	25S-7D5063-02	SMR5063-02	\$4995	Please call
X	X	Horiz Stab – LH	25S-7D5063-03	SMR5063-03	\$2543	Please call
X	X	Horiz Stab – RH	25S-7D5063-04	SMR5063-04	\$2543	Please call
X	X	Vertical Fin	25S-7D5063-05	SMR5063-05	\$2529	Please call
X	X	Horiz Stab – LH	25S-7D5063-09	SMR5063-09	\$2755	Please call
X	X	Horiz Stab – RH	25S-7D5063-10	SMR5063-10	\$2755	Please call

Applicable to aircraft with field installed de-icing system per kit #760-731

Piper PA-31 Navajo Series

PA-31 PA-31-300	PA-31-325	PA-31P	PA-31T	Location:	Goodrich P/N:	SMR P/N:	List:	Your Cost:
	5-7512033	3-7530027	7400002- 7400033, 36, 38					
X	X	X	X	Horiz Stab	23S-2100-3-1	SMR2100-3-1	\$3531	Please call
X	X	X	X	Vertical Fin	23S-2100-4-1	SMR2100-4-1	\$3093	Please call
X	X	X	X	Nac – Tip – LH	23S-2100-5-1	SMR2100-5-1	\$6418	Please call
X	X	X	X	Nac – Tip – RH	23S-2100-5-2	SMR2100-5-2	\$7305	Please call
		X		Nac – Tip – RH	23S-2100-6-2	SMR2100-6-2	\$6472	Please call
FAA requires de-ice boots to be replaced in pairs for all Ice Shield 2 part numbers (replacement option for Goodrich tube-type de-icers).								

Piper PA-31 Navajo/Chieftain Series

PA-31-310	PA-31-325	PA-31-350	PA-31P	Location:	Goodrich P/N:	SMR P/N:	List:	Your Cost:
	7512033 & Up							
X	X	X	X	Nac - Tip – LH	25S-7D5026-01	SMR5026-01	\$6630	Please call
X	X	X	X	Nac - Tip – RH	25S-7D5026-02	SMR5026-02	\$7564	Please call
X	X	X	X	Horiz Stab – LH	25S-7D5026-03	SMR5026-03	\$3635	Please call
X	X	X	X	Horiz Stab – RH	25S-7D5026-04	SMR5026-04	\$3635	Please call
X	X	X	X	Vertical Fin	25S-7D5026-05	SMR5026-05	\$3118	Please call
X	X	X		Fus - Nac – LH	25S-7D5026-07	SMR5026-07	\$2480	Please call
X	X	X		Fus - Nac – RH	25S-7D5026-08	SMR5026-08	\$2480	Please call

Piper PA-31 Navajo/Chieftain Series

PA-31P-350	PA-31T	PA-31 T1 T2	PA-31 T3	Location:	Goodrich P/N:	SMR P/N:	List:	Your Cost:
	7520033- 7520035 7520038 & Up							
	X	X		Engine Inlet	5E1461-1	SMR1416-1	\$2241	Please call
	X	X	X	Nac - Tip - LH	25S-7D5026-01	SMR5026-01	\$6630	Please call
	X*	X*	X	Nac - Tip – RH	25S-7D5026-02	SMR5026-02	\$7564	Please call
X	X	X	X	Horiz Stab – LH	25S-7D5026-03	SMR5026-03	\$3635	Please call
X	X	X	X	Horiz Stab – RH	25S-7D5026-04	SMR5026-04	\$3635	Please call
X	X	X	X	Vertical Fin	25S-7D5026-05	SMR5026-05	\$3118	Please call
X**	X**	X**	X**	Nac - Tip – LH	25S-7D5026-06	SMR5026-06	\$6644	Please call
X			X	Fus - Nac – LH	25S-7D5026-07	SMR5026-07	\$2480	Please call
X			X	Fus - Nac – RH	25S-7D5026-08	SMR5026-08	\$2480	Please call
X				Nac – Tip – LH	25S-7D5026-11	SMR5026-11	\$7586	Please call
X				Nac – Tip – RH	25S-7D5026-12	SMR5026-12	\$8651	Please call
* - SMR5026-02: Stall speed indicator cut-out ** - SMR5026-06: No stall speed indicator								

Piper PA-32R Saratoga Series

301-T	Location:	Goodrich P/N:	SMR P/N:	List:	Your Cost:
X	Wing – LH	25S-5D5123-01	SMR5123-01	\$4493	Please call
X	Wing – RH	25S-5D5123-02	SMR5123-02	\$4493	Please call
X	Horiz Stab – LH	25S-5D5123-03	SMR5123-03	\$2300	Please call
X	Horiz Stab – RH	25S-5D5123-04	SMR5123-04	\$2300	Please call
X	Vertical Fin	25S-5D5123-05	SMR5123-05	\$2346	Please call

Piper PA-34 Seneca Series

PA-34-200, 200T	PA-34-220T	Location:	Goodrich P/N:	SMR P/N:	List:	Your Cost:
X	X	Wing – LH	25S-7D5036-01	SMR5036-01	\$4198	Please call
X	X	Wing – RH	25S-7D5036-02	SMR5036-02	\$4198	Please call
X	X	Horiz Stab – LH	25S-7D5036-03	SMR5036-03	\$3202	Please call
X	X	Horiz Stab – RH	25S-7D5036-04	SMR5036-04	\$3202	Please call
X	X	Vertical Fin	25S-7D5036-05	SMR5036-05	\$2206	Please call
X	X	Wing – LH	25S-7D5036-07	SMR5036-07	\$4198	Please call
X	X	Wing – RH	25S-7D5036-08	SMR5036-08	\$4198	Please call

Piper PA-42 Cheyenne Series

PA-42	PA-42-720	PA-42-1000	Location:	Goodrich P/N:	SMR P/N:	List:	Your Cost:
X	X	X	Fus - Nac – LH	25S-7D5095-09	SMR5095-09	\$5461	Please call
X	X	X	Fus - Nac – RH	25S-7D5095-10	SMR5095-10	\$5461	Please call
X	X	X	Nac - Tip – LH	25S-7D5095-11	SMR5095-11	\$8068	Please call
X	X	X	Horiz Stab – LH	25S-7D5095-13	SMR5095-13	\$5065	Please call
X	X	X	Horiz Stab – RH	25S-7D5095-14	SMR5095-14	\$5065	Please call
X	X	X	Vertical Fin	25S-7D5095-15	SMR5095-15	\$4080	Please call
X	X	X	Nac - Tip – RH	25S-7D5095-18	SMR5095-18	\$8068	Please call

Piper PA-46 Malibu/Mirage/Meridian Series

PA-46-310P	PA-46-350P	PA-46-500TP	Location:	Goodrich P/N:	SMR P/N:	List:	Your Cost:
X	X		Horiz Stab – LH	27S-7D5164-05	SMR5164-05	\$3054	Please call
X	X		Horiz Stab – RH	27S-7D5164-06	SMR5164-06	\$3054	Please call
X	X	X	Vertical Fin	27S-7D5164-07	SMR5164-07	\$2863	Please call
X	X		Wing – LH	27-7D5164-09	SMR5164-09	\$8512	Please call
X	X		Wing – LH Cut Out	27-7D5164-11	SMR5164-11	\$8512	Please call
X*	X*		Wing – RH	27-7D5164-12	SMR5164-12	\$8512	Please call
		X	Horiz Stab – LH	27-7D5294-05	SMR5294-05	\$3300	Please call
		X	Horiz Stab – RH	27-7D5294-20	SMR5294-20	\$3300	Please call
		X	InbdWing – LH	27-7D5294-21	SMR5294-21	\$3676	Please call
		X	InbdWing – RH	27-7D5294-22	SMR5294-22	\$3676	Please call
		X	OutbdWing – LH	27-7D5294-23	SMR5294-23	\$5770	Please call
		X	OutbdWing – RH	27-7D5294-24	SMR5294-24	\$5770	Please call

SMR5164-12: For aircraft without internal radar

Piper PA600 Aerostar Series

PA600	PA600	PA601	PA601	PA601	Location:	Goodrich P/N:	SMR P/N:	List:	Your Cost:
	161-925	1-341	161-925	926 & Up					
X		X			Wing – LH	25S-7D5066-01 23S-2133-1-1	SMR5066-01	\$3413	Please call
X		X			Wing – RH	25S-7D5066-02 23S-2133-1-2	SMR5066-02	\$3413	Please call
X		X	X	X	Horiz Stab	25S-7D5066-03 23S-2133-2-1	SMR5066-03	\$2726	Please call
X		X	X	X	Vertical Fin	25S-7D5066-04 23S-2133-3-1	SMR5066-04	\$2060	Please call
		X	X	X	Wing – LH	25S-7D5066-05	SMR5066-05	\$3906	Please call
		X	X	X	Wing – RH	25S-7D5066-06	SMR5066-06	\$3906	Please call
	X		X		Fus - Nac	25S-7D5066-11	SMR5066-11	\$2519	Please call

Piper PA600, 700 Aerostar

PA601P	PA601P	PA601P	PA602P	PA700P	Location:	Goodrich P/N:	SMR P/N:	List:	Your Cost:
1-156	157-212	213 & Up							
X	X				Wing – LH	25S-7D5066-01 23S-2133-1-1	SMR5066-01	\$3413	Please call
X	X				Wing – RH	25S-7D5066-02 23S-2133-1-2	SMR5066-02	\$3413	Please call
X	X	X	X	X	Horiz Stab LH/RH	25S-7D5066-03 23S-2133-2-1	SMR5066-03	\$2726	Please call
X	X	X	X	X	Vertical Fin	25S-7D5066-04 23S-2133-3-1	SMR5066-04	\$2060	Please call
	X	X	X	X	Wing – LH	25S-7D5066-05	SMR5066-05	\$3906	Please call
	X	X	X		Wing – RH	25S-7D5066-06	SMR5066-06	\$3906	Please call
		X	X	X	Fus – Nac LH/RH	25S-7D5066-11	SMR5066-11	\$2519	Please call
				X*	Nac – Tip – RH	25S-7D5066-14	SMR5066-14	\$4017	Please call

*S/N 1027 & Up

Vulcanair P68 Partenavia Series

P68 Victor	P68B Victor	P68C	P68R Victor	P68C-TC	Location:	Goodrich P/N:	SMR P/N:	List:	Your Cost:
X	X	X	X	X	Nac – Light – LH	25S-5D5039-01	SMR5039-01	\$2844	Please call
X	X	*X	**X	****X	Light-TipWing-LH	25S-5D5039-03	SMR5039-03	\$3706	Please call
X	X	*X	**X		Nac-TipWing-RH	25S-5D5039-04	SMR5039-04	\$5230	Please call
X	X	X	X	X	Horiz Stab LH/RH	25S-5D5039-05	SMR5039-05	\$2844	Please call
X	X	X	X	X	Vertical Fin	25S-5D5039-07	SMR5039-07	\$3789	Please call
				****X	Nac-TipWing-RH	25S-5D5039-08	SMR5039-08	\$5437	Please call
		*****X	***X	****X	Light-TipWing-LH	25S-5D5039-09	SMR5039-09	\$4590	Please call
		*****X	***X		Nac-TipWing-RH	25S-5D5039-10	SMR5039-10	\$3657	Please call
				****X	Nac-TipWing-RH	25S-5D5039-12	SMR5039-12	\$3437	Please call

*Up to S/N 250, excluded S/N 243; **Only S/N 40; ***From S/N 430; ****Up to S/N 312; *****From S/N 313; *****From S/N 251 plus S/N 243

Vulcanair P68 Partenavia Series

P68 Observer	P68 Observer 2	P68TC Observer	AP68TP 300 Spartacus	AP68TP 600 Viator	Location:	Goodrich P/N:	SMR P/N:	List:	Your Cost:
X	X	X			Nac – Light – LH	25S-5D5039-01	SMR5039-01	\$2844	Please call
*X					Light-TipWing-LH	25S-5D5039-03	SMR5039-03	\$3706	Please call
*X					Nac-TipWing-RH	25S-5D5039-04	SMR5039-04	\$5230	Please call
X	X	X			Horiz Stab LH/RH	25S-5D5039-05	SMR5039-05	\$2844	Please call
X	X	X			Vertical Fin	25S-5D5039-07	SMR5039-07	\$3789	Please call
**X	X	X			Light-TipWing-LH	25S-5D5039-09	SMR5039-09	\$4590	Please call
**X	X				Nac-TipWing-RH	25S-5D5039-10	SMR5039-10	\$3657	Please call
		X			Nac-TipWing-RH	25S-5D5039-12	SMR5039-12	\$3437	Please call
			X	X	OutbdWing – LH	25S-5D5181-01	SMR5181-01	\$3643	Please call
			X	X	OutbdWing – RH	25S-5D5181-02	SMR5181-02	\$3643	Please call
			X	X	Horiz Stab – LH	25S-5D5181-03	SMR5181-03	\$2081	Please call
			X	X	Horiz Stab – RH	25S-5D5181-04	SMR5181-04	\$2081	Please call
			X	***X	Vertical Fin	25S-5D5181-05	SMR5181-05	\$1686	Please call
			X	X	InbdWing – LH	25S-5D5181-07	SMR5181-07	\$1213	Please call
			X	X	InbdWing – RH	25S-5D5181-08	SMR5181-08	\$1213	Please call
				****X	Vertical Fin	25S-5D5181-09	SMR5181-09	\$1530	Please call

*Up to S/N 250, excluded S/N 243; **From S/N 251 plus S/N 243; ***Only S/N 9001 and 9002; ****From S/N 9003



PROPELLER DE-ICERS

SMR	Goodrich	Safeway	Rapco	McCauley	Various	Description	List:	Your Cost:
SMR1188-1	4E1188-1	N/A	N/A	N/A	N/A	Wire Element – Integral Lead	\$327	Please call
SMR1188-2	4E1188-2	N/A	N/A	N/A	N/A	Wire Element – Integral Lead	\$327	Please call
SMR1188-3	4E1188-3	6848 6959	RA1288-3	N/A	N/A	Wire Element – Integral Lead	\$327	Please call
SMR1188-4	4E1188-4	6904	RA1288-4	N/A	N/A	Wire Element – Integral Lead	\$327	Please call
SMR1188-5	4E1188-5	5735 6975 (QDS)	RA1288-5	N/A	N/A	Wire Element – Integral Lead	\$327	Please call
SMR1188-6	4E1188-6	6860	RA1288-6	N/A	N/A	Wire Element – Integral Lead	\$327	Please call
SMR1188-7	4E1188-7	6905	RA1288-7	N/A	N/A	Wire Element – Wire Leads	\$327	Please call
SMR1214-1	4E1214-1	6980	N/A	N/A	N/A	Wire Element – Integral Lead	\$327	Please call
SMR1214-2	4E1214-2	6981	RA1314-2	N/A	N/A	Wire Element – Integral Lead	\$327	Please call
SMR1214-3	4E1214-3	6982	RA1314-3	N/A	N/A	Wire Element – Integral Lead	\$327	Please call
SMR1214-4	4E1214-4	N/A	N/A	N/A	N/A	Wire Element – Integral Lead	\$327	Please call
SMR1214-7	4E1214-7	6983	N/A	N/A	N/A	Wire Element – Wire Leads	\$327	Please call
SMR1214-10	4E1214-10	N/A	N/A	N/A	N/A	Wire Element – QDS Connector	\$327	Please call
SMR1319	5E1319	N/A	N/A	N/A	N/A	Engine Inlet Anti-icer	\$1134	Please call
SMR1346	5E1346	N/A	N/A	N/A	N/A	DeHavilland Engine Inlet	\$1702	Please call
SMR1461-1	5E1461-1	N/A	N/A	N/A	N/A	Engine Inlet Anti-icer	\$2241	Please call
SMR1601-3	4E1601-3	6888	RA1701-3	N/A	N/A	Wire Element – Integral Lead	\$327	Please call
SMR1601-4	4E1601-4	N/A	N/A	N/A	N/A	Wire Element – Integral Lead	\$327	Please call
SMR1601-5	4E1601-5	6908	N/A	N/A	N/A	Wire Element – Integral lead	\$327	Please call
SMR1601-7	4E1601-7	6870	RA1701-7	N/A	N/A	Wire Element – Wire Leads	\$327	Please call
SMR1601-10	4E1601-10	6906	N/A	N/A	N/A	Wire Element – QDS Connector	\$327	Please call
SMR1601-14	4E1601-14	N/A	N/A	N/A	N/A	Wire Element – Integral Lead	\$327	Please call
SMR1601-14	4E1601-14	N/A	N/A	N/A	N/A	Wire Element – Integral Lead	\$327	Please call
SMR1683-1	5E1683-1	N/A	N/A	N/A	N/A	Engine Inlet Anti-icer	\$1723	Please call
SMR1895-2	4E1895-2	6985	RA1995-2	N/A	N/A	Wire Element – Integral Lead	\$327	Please call
SMR1895-7	4E1895-7	6986	N/A	N/A	N/A	Wire Element – Wire Leads	\$327	Please call
SMR1895-10	4E1895-10	N/A	N/A	N/A	N/A	Wire Element – QDS Connector	\$327	Please call
SMR1956-4	4E1956-4	5855BSW 6615SW	RA2056-4	B-40183-04	C165013- 0601	Wire Element – Integral Lead	\$310	Please call
SMR2152-2	4E2152-2	6936SW	RA2252-2	B-40183-05	N/A	Wire Element – Wire Leads	\$333	Please call
SMR2152-4	4E2152-4	6935SW	RA2252-4	B-40183-03 (-06)	N/A	Wire Element – Wire Leads	\$319	Please call
SMR2200-3	4E2200-3	N/A	N/A	N/A	N/A	Etched Foil – Integral Lead	\$387	Please call
SMR2200-4	4E2200-4	6881SW	N/A	N/A	N/A	Etched Foil – Integral Lead	\$387	Please call
SMR2200-10	4E2200-10	6900	N/A	N/A	N/A	Etched Foil – QDS Connector	\$387	Please call
SMR2200-21	4E2200-21	N/A	N/A	N/A	N/A	Etched Foil – QDS Connector	\$387	Please call
SMR2263	N/A	N/A	N/A	N/A	N/A	Etched Foil – Integral Lead	\$387	Please call
SMR2271-10	4E2271-10	6901	N/A	N/A	N/A	Etched Foil – QDS Connector	\$387	Please call
SMR2271-13	4E2271-13	N/A	N/A	N/A	N/A	Etched Foil	\$387	Please call
SMR2292-2	4E2292-2	N/A	N/A	N/A	N/A	Etched Foil – Integral Lead	\$387	Please call
SMR2292-3	4E2292-3	N/A	N/A	N/A	N/A	Etched Foil – Integral Lead	\$387	Please call
SMR2292-10	4E2292-10	6988	N/A	N/A	N/A	Etched Foil – QDS Connector	\$387	Please call
SMR2303-10	4E2303-10	6989	N/A	N/A	N/A	Etched Foil – QDS Connector	\$387	Please call
SMR2336-12	4E2336-12	6892	N/A	N/A	N/A	Etched Foil – QDS Connector	\$387	Please call
SMR2351-3	4E2351-3	N/A	N/A	N/A	N/A	Etched Foil – Integral Lead	\$387	Please call
SMR2560-10	4E2560-10	6893	N/A	N/A	N/A	Etched Foil – QDS Connector	\$420	Please call
SMR2560-12	4E2560-12	6894SW	N/A	B-40245-54	N/A	Etched Foil – QDS Connector	\$420	Please call
SMR2575-7	4E2575-7	N/A	N/A	N/A	N/A	Etched Foil – Wire Leads	\$420	Please call
SMR2575-10	4E2575-10	N/A	N/A	N/A	N/A	Etched Foil – QDS Connector	\$420	Please call
SMR2595-7	4E2595-7	6880	N/A	N/A	N/A	Etched Foil – Wire Leads	\$387	Please call
SMR2598-10	4E2598-10	6984	N/A	N/A	N/A	Etched Foil – QDS Connector	\$487	Please call
SMR2702	4E2702	6592SW	RA2948	B-40183-19 (-01)	N/A	Wire Element – Integral Lead	\$333	Please call
SMR2715-1	4E2715-1	6199SW	RA2815-1	N/A	C165013- 0701	Wire Element – Integral Lead	\$319	Please call
SMR2715-2	4E2715-2	6623SW	N/A	N/A	C165013- 0705	Wire Element – Integral Lead	\$320	Please call
SMR2716	4E2716	6205SW	RA2252-2	B-40183-02	6205	Wire Element – Integral Lead	\$419	Please call
SMR2762-10	4E2762-10	N/A	N/A	N/A	N/A	QDS Connector	\$554	Please call
SMR2822	4E2822	6717SW	N/A	B-40183-07	N/A	Wire Element – Wire Leads	\$428	Please call
SMR3017-1	4E3017-1	N/A	N/A	N/A	N/A	Prop De-Icer	\$607	Please call
SMR3051-10	4E3051-10	N/A	N/A	N/A	N/A	Etched Foil	\$387	Please call
SMR3400-1	4E3400-1	N/A	N/A	N/A	N/A	Prop De-Icer	\$607	Please call
SMR37572	37572	N/A	N/A	N/A	N/A	Alcohol Feed Shoe	\$93	Please call
SMR40183-16	N/A	N/A	N/A	B-40183-16	N/A	Wire Element – Wire Leads	\$493	Please call

SMR40183-17	N/A	N/A	N/A	B-40183-17	N/A	Wire Element – Wire Leads	\$493	Please call
SMR40183-55	N/A	N/A	N/A	B-40183-55	N/A	Wire Element – Wire Leads	\$490	Please call
SMR40245-56	N/A	N/A	N/A	B-40245-56	N/A	Etched Foil – QDS Connector	\$490	Please call
SMR6658	N/A	6658SW	N/A	B-40245-50	N/A	Etched Foil – Wire Leads	\$333	Please call
SMR6662	N/A	6662SW	N/A	B-40245-52	N/A	Etched Foil – Wire Leads	\$333	Please call
SMR6663	N/A	6663SW	N/A	B-40245-53	N/A	Etched Foil – Wire Leads	\$395	Please call
SMR6722	N/A	6722SW	N/A	B-40183-08	N/A	Wire Element – Wire Leads	\$393	Please call
SMR6885	N/A	6885	N/A	N/A	N/A	Wire Leads, Wire Element	\$479	Please call
SMR6890	N/A	6890	N/A	N/A	660716276	Wire Element – Wire Leads	\$437	Please call
SMR6975-10R	6975-10R	N/A	N/A	N/A	N/A	Replacement QDS Kit Containing Propeller Boot SMR6975-11 and Wire Harness SMR6976-11	\$521	Please call
SMR6975-11	4E6975-11	N/A	N/A	N/A	N/A	Wire Element – QDS Connector	\$327	Please call
SMR715841	N/A	715841SW	N/A	N/A	715841	Braided Wire Leads	\$1255	Please call
SMR802252-4	N/A	802252SW-4	N/A	N/A	N/A	Etched Foil – Wire Leads	\$2443	Please call
SMR802337-2	N/A	802337-2SW	N/A	N/A	N/A	Etched Foil – Integral Lead	\$3252	Please call
SMR9050	N/A	N/A	N/A	N/A	N/A	Etched Foil – Integral Lead 28V	\$388	Please call

WIRE HARNESS

SMR	Goodrich	Safeway	Rapco	McCauley	Various	Description	List:	Your Cost:
SMR1889-2	4E1889-2	7021	RA1989-2	N/A	N/A	3 wire assy with ring terminals	\$87	Please call
SMR1889-3	4E1889-3	6959	RA1989-3	N/A	N/A	3 wire assy with ring terminals	\$87	Please call
SMR1889-4	4E1889-4	6871	RA1989-4	N/A	N/A	3 wire assy with ring terminals	\$87	Please call
SMR1889-7	4E1889-7	6995	N/A	N/A	N/A	3 wire assy with ring terminals	\$74	Please call
SMR1967-1	4E1967-1	6962	RA2067-1	N/A	N/A	3 wire kit with ring terminals	\$89	Please call
SMR1967-2	4E1967-2	6963	RA2067-2	N/A	N/A	3 wire kit with ring terminals	\$72	Please call
SMR1967-3	4E1967-3	6964	RA2067-3	N/A	N/A	3 wire kit with socket connector	\$89	Please call
SMR1967-4	4E1967-4	6965	RA2067-4	N/A	N/A	3 wire kit with ring terminals	\$89	Please call
SMR1967-5	4E1967-5	6966	RA2067-5	N/A	N/A	3 wire kit with ring terminals	\$128	Please call
SMR2017-4	3E2017-4	6881	RA2117-4	N/A	N/A	2 wire assy with ring terminals	\$94	Please call
SMR2017-8	3E2017-8	6951	RA2117-8	N/A	N/A	2 wire assy with ring terminals	\$119	Please call
SMR2050	3E2050	6960	RA2150	N/A	N/A	2 wire kit with socket connector	\$77	Please call
SMR2050-2	3E2050-2	6961	RA2150-2	N/A	N/A	2 wire kit with socket connector	\$77	Please call
SMR2071-1	4E2071-1	6260SW-1	RA-C165013-0602	N/A	C165013-0602	3 wire assy with ring terminals	\$106	Please call
SMR2071-2	4E2071-2	N/A	RA2171-2	N/A	N/A	3 wire assy with ring terminals	\$111	Please call
SMR2071-3	4E2071-3	6479SW	RA-C165013-0604	B-5051	C165013-0604	3 wire assy with ring terminals	\$111	Please call
SMR2092-1	3E2092-1	7022	RA2192-1	N/A	N/A	2 wire assy with socket connector	\$70	Please call
SMR2092-2	3E2092-2	6887	RA2192-2	N/A	N/A	2 wire assy with socket connector	\$87	Please call
SMR2092-3	3E2092-3	6952	RA2192-3	N/A	N/A	2 wire assy with socket connector	\$87	Please call
SMR2092-4	3E2092-4	6834	RA2192-4	N/A	N/A	2 wire assy with socket connector	\$87	Please call
SMR2092-5	3E2092-5	6953	RA2192-5	N/A	N/A	2 wire assy with socket connector	\$70	Please call
SMR2092-6	3E2092-6	6954	RA2192-6	N/A	N/A	2 wire assy with socket connector	\$87	Please call
SMR2092-9	3E2092-9	N/A	N/A	N/A	N/A	2 wire assy with socket connector	\$106	Please call
SMR2093-1	3E2093-1	6992	N/A	N/A	N/A	2 wire assy with socket connector	\$106	Please call
SMR2094-1	3E2094-1	6955	RA2194-1	N/A	N/A	2 wire assy with socket connector	\$70	Please call
SMR2094-2	3E2094-2	6956	RA2194-2	N/A	N/A	2 wire assy with socket connector	\$106	Please call
SMR2094-3	3E2094-3	6993	RA2194-3	N/A	N/A	2 wire assy with socket connector	\$70	Please call
SMR2235-3	4E2235-3	N/A	N/A	N/A	N/A	3 wire assy with socket connector	\$89	Please call
SMR2293-1	3E2293-1	6875SW	RA40387	B-40387	N/A	2 wire assy with ring/hook terminals	\$138	Please call
SMR2333-1	3E2333-1	6957	N/A	N/A	N/A	3 wire assy with socket connector	\$106	Please call
SMR2360-4	3E2360-4	N/A	N/A	N/A	N/A	2 wire assy with socket connector	\$89	Please call
SMR2369-1	4E2369-1	6987	RA2469-1	N/A	N/A	3 wire assy with socket connector	\$94	Please call
SMR2369-2	4E2369-2	6941	RA2469-2	N/A	N/A	3 wire assy with socket connector	\$74	Please call
SMR2369-4	4E2369-4	N/A	N/A	N/A	N/A	3 wire assy with socket connector	\$94	Please call
SMR2369-5	4E2369-5	N/A	N/A	N/A	N/A	3 wire assy with socket connector	\$94	Please call
SMR2370-4	3E2370-4	N/A	N/A	N/A	N/A	2 wire kit with socket connector	\$89	Please call
SMR2526-1	3E2526-1	N/A	RA2626-1	N/A	N/A	2 wire assy with ring terminals	\$94	Please call
SMR40276	N/A	6659SW-1	N/A	B-40276	N/A	2 wire assy with ring terminals	\$138	Please call
SMR40330	N/A	6719SW	RA40330	B-40330	N/A	2 wire assy with ring/hook terminals	\$266	Please call
SMR40531	N/A	N/A	N/A	B-40531	N/A	2 wire assy with socket connector	\$111	Please call
SMR40585	N/A	N/A	N/A	B-40585	N/A	2 wire assy with socket connector	\$138	Please call
SMR6976-11	N/A	6976-11	N/A	N/A	N/A	Wire Harness	\$79	Please call

ACCESSORIES

SMR	Goodrich	Safeway	Rapco	McCauley	Various	Description	List:	Your Cost:
2MA1414-01	N/A	N/A	N/A	N/A	N/A	De-Icer Installation kit	\$593	Please call
2MA1414-12	N/A	N/A	N/A	N/A	N/A	Swab, 10 Pack Kit, EDI/PDI	\$56	Please call
2MA1419-01	N/A	N/A	N/A	N/A	N/A	Wing De-Icer Repair Kit	\$855	Please call
2MA1419-02	N/A	N/A	N/A	N/A	N/A	Wing De-Icer Repair Kit No Primer	\$767	Please call
2MA1425-02	N/A	N/A	N/A	N/A	N/A	Wing De-Icer Adhesive Kit With Tools	\$173	Please call
2MA1425-03	N/A	N/A	N/A	N/A	N/A	Wing De-Icer Adhesive Kit Without Tools	\$110	Please call
2MA1425-04	N/A	N/A	N/A	N/A	N/A	Propeller Boot Adhesive Kit with Tools	\$126	Please call
4MA1929-01	N/A	N/A	N/A	N/A	N/A	Qty 10 ea 5 x 10 in Repair Patches	\$312	Please call
4MA1929-02	N/A	N/A	N/A	N/A	N/A	Qty 30 ea 2.5 x 5 in Repair Patches	\$254	Please call
4MA1929-03	N/A	N/A	N/A	N/A	N/A	Qty 30 ea 1.25 x 2.5 in Repair Patches	\$147	Please call
4MA2043-1	2E1260	N/A	N/A	N/A	N/A	Nylon Bushing	\$21	Please call
4MA2181-1	N/A	N/A	N/A	B-5024	N/A	Nylon Bushing	\$21	Please call
SMR-A56B-P	N/A	N/A	N/A	N/A	N/A	½ Pint Conductive Edge Sealer (Shipped FOB Destination via UPS Ground Within Continental US)	\$314	Please call
SMR-A56B-Q	N/A	N/A	N/A	N/A	N/A	1 Quart Conductive Edge Sealer (Shipped FOB Destination via UPS Ground Within Continental US)	\$543	Please call
SMR1319	5E1319	N/A	N/A	N/A	N/A	Engine Inlet Anti-Icer	\$1134	Please call
SMR1346	5E1346	N/A	N/A	N/A	N/A	DeHavilland Engine Inlet Anti-icer	\$1702	Please call
SMR1461-1	5E1461-1	N/A	N/A	N/A	N/A	Engine Inlet Anti-Icer	\$2241	Please call
SMR1683-1	5E1683-1	N/A	N/A	N/A	N/A	Engine Inlet Anti-Icer	\$1723	Please call
SMR2353-06	3D2353-06	N/A	N/A	N/A	N/A	Ejector Flow Control Valve	\$2339	Please call
SMR37572	37572	N/A	N/A	N/A	N/A	Alcohol Feed Shoe	\$93	Please call
SMR6200	N/A	6200SW	N/A	N/A	N/A	Restrainer Strap ~ 12 inch	\$34	Please call
SMR6201	N/A	6201SW	N/A	N/A	N/A	Restrainer Strap ~ 24 inch	\$34	Please call
SMR6202	N/A	6202SW	N/A	N/A	N/A	Shim	\$28	Please call
SMRPLUS-22	N/A	N/A	N/A	N/A	N/A	Ice Shield Plus 22 oz. Spray Bottle – Ice Adhesion Reduction System	\$192	Please call
SMRPLUS-32	N/A	N/A	N/A	N/A	N/A	Ice Shield Plus 32 oz. Container – Ice Adhesion Reduction System	\$300	Please call

de-icing systems